

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Port Fourchon Waste Staging Area	Facility Location ID:	FouW01
Assessment Date :	8/22/2010	Incident Name :	BP Spill
Physical Location :	570 Dudley Bernard Rd. (facility is actually located in Port Fourchon at the port)		
City, State :	Golden Meadow, LA	County :	LaFourche

ASSESSMENT INFORMATION

General Site Information and Observations			
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/>	Yes	<input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/>	Yes	<input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0		
Additional Comments : WASR arrived at the waste collection and staging area located in Port Fourchon, LaFrouche Parish, LA (FouW01, coordinates: 29.139274N, -90.208114W) at 1225 hours. WASR met with BP waste disposal contractors from Heritage Environmental. WASR inquired if the waste coordinators had received any communications regarding the status of frac tank hatches; Heritage stated that they had received notification late on 8/21/2010 that all frac tank hatches/lids are to remain closed unless actively being loaded/unloaded, gauged, or sampled. An inspection of the frac tanks at FouW01 found that the hatch on frac tank 259584 was open. Heritage immediately corrected the open hatch. WASR departed the site at 1245 hours.			